

CABINET DOOR PLUS

REQUIRED MATERIAL


1 PROFILE PLUS 4



2 GLASS *(Emuca does not commercialize this item)*




3 GASKET FOR PLUS 4 - 7



4


CORNERS FOR PLUS 4 - 11 - 14




FULL OVERLAY HINGE X91 WITH SOFT CLOSE




1 PROFILE PLUS 7



2 GLASS *(Emuca does not commercialize this item)*




3 GASKET FOR PLUS 4 - 7



4


CORNERS FOR PLUS 7




FULL OVERLAY HINGE X91N




1 PROFILE PLUS 11



2 GLASS *(Emuca does not commercialize this item)*




3 GASKET FOR PLUS 11



4


CORNERS FOR PLUS 4 - 11 - 14




FULL OVERLAY HINGE X91 WITH SOFT CLOSE




1 PROFILE PLUS 14



2 GLASS *(Emuca does not commercialize this item)*




3 Double sided adhesive tape FOR PLUS 14



4

CORNERS FOR PLUS 4 - 11 - 14




FULL OVERLAY HINGE X91 WITH SOFT CLOSE




MATERIAL PREPARATION


1 CUTTING OF ALUMINIUM PLUS PROFILES


PLUS 4 **PLUS 11** **PLUS 14**






PLUS 7






2 CUTTING GLASS

(Emuca does not commercialize this item)






PLUS 4
A - 6mm
B - 6mm


PLUS 7
A - 27mm
B - 27mm

PLUS 11
A - 3mm
B - 3mm

PLUS 14
A - 4mm
B - 4mm


3 FITTING THE GASKET









PLUS 4



PLUS 7




PLUS 11




4

PLUS 4 + GASKET




x4



x4

PLUS 7 + GASKET




x4




x4


PLUS 11 + GASKET



x4



x4




4mm




x8 for brackets


PLUS 14 + adhesive



x4



x4



4mm



x8 for brackets

PLUS 4 - 11 - 14



x2 o x3


PLUS 7




x2 o x3




x for Hinges





PLUS 4 - 11 - 14



PLUS 7

