



Manufacturer:
Speedball®
Product Name:
Speedball Soft Rubber Brayer with Steel Frame - 3 inch
Manufacturer Part Number:
36571

▶ [Click here for more details on the ÅngströmLap Sequoia 0.2um Diamond Lapping Film, 4" Disk with PSA Backing single sheet](#)

**MATERIAL SAFETY DATA SHEET
(MSDS)
Speedball Brayer Soft Rubber**

I. COMPANY AND PRODUCT IDENTIFICATION

Company : Speedball Art Products
2301 Speedball Rd
Statesville, NC 28677

Tel: 800-898-7224

Date: January 2, 2012

Product: Rubber Roller Soft

Chemical Name: Natural Rubber

Trade Names: RMA IX

Emergency Phone Number: 800-898-7224

II. INGREDIENTS / IDENTITY INFORMATION

Major components: Natural Rubber

Minor Components: Zinc Oxide
Sulfur
Hydrocarbon Process Oil
Accelerators / Activators (< 1%)
Antioxidant / Stabilizers (< 1%)

Contact the professionals at Fiber Optic Center for a quote or to get more details.

23 Centre Street • New Bedford, MA 02740 USA • focenter.com
508-992-6464 | (800) 473-4237 • sales@focenter.com



Data is subject to change without notice. FOC last update 2/5/2026.

SAFETY DATA SHEET (SDS)

**Manufacturer:**

Speedball®

Product Name:

Speedball Soft Rubber Brayer with Steel Frame - 3 inch

Manufacturer Part Number:

36571

▶ [Click here for more details on the ÅngströmLap Sequoia 0.2um Diamond Lapping Film, 4" Disk with PSA Backing single sheet](#)

III. PHYSICAL PROPERTIES

Appearance	:	Flexible rubber rolls
Odor	:	Slight typical rubber product odor
Specific Gravity	:	1.10-1.20
Boiling Point	:	N/A
Melting Point	:	N/A
Decomposition Temperature	:	> 250 °C
Vapor Pressure	:	N/A
Percent Volatile	:	N/A
Solubility in water	:	Insoluble

IV. FIRE AND EXPLOSION HAZARD DATA

Flash Point	:	> 300 ° C
Lower Explosion Limit	:	N/A
Upper Explosion Limit	:	N/A
Fire Hazard :	:	Stable under normal situation flammable / combustible under high heat and flame. Can generate toxic and combustible fumes, - Carbon monoxide nitrogen and hydrocarbon compounds, and soot.
Fire Fighting Procedures	:	Use full protective equipment filter masks etc.
Extinguishing Media	:	High expansion Foam, water fog and spray.

V. HEALTH HAZARDS

Contact:	:	Wash hands with mild soap after handling. Avoid contact with eyes. If the eyes are irritated flush with water for ten minutes. Obtain medical attention. Avoid ingestion. If ingested seek medical attention.
Inhalation	:	Work in well-ventilated area.

VI. REACTIVITY AND STABILITY

Stability	:	Product is non-reactive with non-polar chemicals and aqueous solutions. Do not use in contact with gasoline and hydrocarbon solvents.
-----------	---	--

Contact the professionals at Fiber Optic Center for a quote or to get more details.

23 Centre Street • New Bedford, MA 02740 USA • focenter.com

508-992-6464 | (800) 473-4237 • sales@focenter.com



Data is subject to change without notice. FOC last update 2/5/2026.

SAFETY DATA SHEET (SDS)

**Manufacturer:**

Speedball®

Product Name:

Speedball Soft Rubber Brayer with Steel Frame - 3 inch

Manufacturer Part Number:

36571

▶ [Click here for more details on the ÅngströmLap Sequoia 0.2um Diamond Lapping Film, 4" Disk with PSA Backing single sheet](#)

Reactivity: : Stable under normal situation. Flammable and Combustible. Store below 35° C in cool, dry location.

VII. WASTE DISPOSAL

: Disposal must be in accordance with, state and local regulations.
Bury waste in approved landfill site.
Do not incinerate.

VIII. PROTECTIVE EQUIPMENT

Ventilation : : Local and general ventilation is necessary to keep air concentration below level of concern.

IX. STORAGE AND TRANSPORTATION

Package product in paper, plastic film, or box in order to minimize surface exposure store in cool dry, ventilation area.

X. INFORMATION

With appropriate commercial practices, the natural rubber materials and products are safe to handle and in storage.

*Fiber
optic
center*

Contact the professionals at Fiber Optic Center for a quote or to get more details.

23 Centre Street • New Bedford, MA 02740 USA • focenter.com

508-992-6464 | (800) 473-4237 • sales@focenter.com



Data is subject to change without notice. FOC last update 2/5/2026.