

# Disassemble instructions

## The preparation of the instruments:

Instruments: cross screwdriver( $\phi 5\text{mm}$ ) 1pcs




### 1. Whole lamp



2. Loosen M4 screws on the cover, take off the cover and tempered glass.



3. Loosen M3 screws on the pcb board,take off pcb board.



4.Light source module、 Heat sink、 Tempered glass.

