

Disassemble instructions

The preparation of the instruments:


Instruments: cross screwdriver($\phi 5\text{mm}$) 1pcs




1. Whole lamp



2.Loosen U-shaped clips on the heat sink,take off the tempered glass.



3. Loosen M3 screws on the pcb board,take off pcb board.



4.Light source module、 Heat sink、 Tempered glass.

