


# Disassemble instructions

## The preparation of the instruments:

Instruments: cross screwdriver( $\phi 5\text{mm}$ ) 1pcs




### 1. Whole lamp



### 2. Loosen 12pcs M4 screws on the lens, take off the lens.



3. Loosen 12pcs M3 screws on the pcb board,take off pcb board.



4.Light source module、Heat sink、 Lens.

