

Tray

1

TRAY 35

Ø50

2

TRAY 55

Ø62

A

C

CONNECT

220 V~
240

NO DIM

3

DIMMER (NOT INCLUDED)

L N + -

POWER SUPPLY

DIM DALI

L N PRI
DA DA
DA

POWER SUPPLY

FOLLOW DRIVER'S CONNECTION DIAGRAM

4

ADJUST CABLE LENGTH

A

B

C

CONNECT

220 V~
240

NO DIM

3

DIMMER (NOT INCLUDED)

L N + -

POWER SUPPLY

DIM DALI

L N PRI
DA DA
DA

POWER SUPPLY

5

ADJUST CABLE LENGTH

A

B

C

CONNECT

220 V~
240

NO DIM

3

DIMMER (NOT INCLUDED)

L N + -

POWER SUPPLY

DIM DALI

L N PRI
DA DA
DA

POWER SUPPLY

4

ADJUST CABLE LENGTH

A

REMOVE PROTECTION

B

C

6

ADJUST LUMINAIRE HEIGHT

Tray Base

1

ADJUST LUMINAIRE HEIGHT

2

ADJUST LUMINAIRE HEIGHT

A

B

C

D

E

F

G

H

X2

X2

X2

X2

X2

X2

X2

X2

NO DIM 3a

CONNECT

220 V~
240

DIMMER (NOT INCLUDED)

L N + -

POWER SUPPLY

DIM DALI 3b

CONNECT

220 V~
240

DIMMER (NOT INCLUDED)

L N + -

POWER SUPPLY

4

ADJUST LUMINAIRE HEIGHT

5

ADJUST LUMINAIRE HEIGHT

6

ADJUST LUMINAIRE HEIGHT

7

LOCK

8

ADJUST LUMINAIRE HEIGHT

1

TRIMLESS TOOL D20 X D52mm

2

ADJUST LUMINAIRE HEIGHT

3

ADJUST LUMINAIRE HEIGHT

4

ADJUST LUMINAIRE HEIGHT

5

ADJUST LUMINAIRE HEIGHT

6

ADJUST LUMINAIRE HEIGHT

7

ADJUST LUMINAIRE HEIGHT

8

CLEAN THE INNER SURFACE

9

ADJUST CABLE LENGTH

10

ADJUST CABLE LENGTH

11

ADJUST LUMINAIRE HEIGHT

12

ADJUST LUMINAIRE HEIGHT

13

CONNECT

220 V~
240

NO DIM

13

DIMMER (NOT INCLUDED)

L N + -

POWER SUPPLY

DIM DALI

L N PRI
DA DA
DA

POWER SUPPLY

14

ADJUST LUMINAIRE HEIGHT